

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	48	(lamp with portable) and (mount\$3 with (belt or harness))	US-PGPUB; USPAT; USOOR	OR	OFF	2008/03/26 15:03
S1	328	(arc near3 lamp) and ((DC? DC or boost\$3 or flyback or fly-back) near3 conver \$5) and (high near3 (voltage or power))	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 05:34
S2	189	S1 and @AD<"20030926"	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 05:35
S3	179	S2 and (run\$4 or operat \$3) and (start\$3 or ignit \$3)	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 05:38
S4	33	(arc adj lamp) with search \$3	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 06:23
S5	86	(arc adj lamp) with portable	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 06:28
S6	86	S5 not S4	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 06:28
S7	50	S6 and @AD<"20030926"	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 06:28
S8	37	(arc adj lamp) with (belt or harness)	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 06:32
S9	34	(arc near3 lamp) and ((DC? DC or boost\$3 or flyback or fly-back) near3 conver \$5) and (high near3 (voltage or power)) and (run\$4 or operat\$3) and (start\$3 or ignit\$3) and (gas near3 tube)	US-PGPUB; USPAT; USOOR	OR	ON	2008/03/26 06:38
S11	28	lamp and (cable with breakdown with voltage)	US-PGPUB; USPAT; USOOR	OR	OFF	2008/03/26 13:22
S12	19	lamp and ((breakdown near3 voltage) with cable)	US-PGPUB; USPAT; USOOR	OR	OFF	2008/03/26 13:37

3/26/2008 3:46:43 PM

C:\Documents and Settings\lile16\My Documents\EAST\Workspaces\10573126.wsp